

Application for Fitness Certificate of School Buildings (To be Filled in by the Manager)

1. Name of School
2. Location with Name of Education dist./sub District
3. Whether fitness certificate has been issued in previous Years and if so the No. and date of the last certificate and the authority who issued it, Classification of the building and size (basis of classification see Annexure - 1)
 - (i) Permanent (single or multistoreyed)
 - (ii) Semi - permanent
 - (iii) Temporary shed
4. Years of construction of different buildings
5. Short Specification (Score of the specification not applicable)
6.
 - (i) Foundation and Basement
Rubble in lime mortar / Cement / mud mortar or later in Lime mortar/Cement / mud mortar
 - (ii) Superstructure
Rubble in lime/cement /mud or brick/laterite in lime cement/mud or brick in lime cement for pillars with intermediate walls with sun-dried bricks
 - (iii) Doors and windows/country wood (mention specifics)
 - (iv) Wood Work Wrought and put up / Country Wood (mention species wrought and put up/country Wood of wrought and put up & full or half bamboo for rafters iron trusses)
 - (v) Kind of roof with short specification of materials used
R. C. C. / Tiled (Teached AC sheets)
- (vi) Floorings
Cement plastered over / Hard broken stone concrete bedding / General concrete Gravel bedding/laterite
7. Whether regular maintenance attended to or not, period during

AMRITA VIDYALAYAM

PANCHIKKAL, AYYANTHOLE

THRASSUR - Block A.

Class room - 6.50 X 3.35 X 3.6 (6 Nos)
 Staff Room - 6.50 X 3.35 X 3.6 (3 Nos)
 Chemistry Room - 6.35 X 13.23 X 3.6 (1 Nos)
 Office Room - 6.50 X 6.35 X 3.6 (1 Nos)
 Principal Room - 6.50 X 6.35 X 3.6 (1 Nos)
 Permanent
 Passage Room - 3.19 X 6.50 X 3.6 (1 Nos)

Three Storeyed build upto the height of 9.30mts.

Rubble in Cement Mortar

Rcc pillars with intermediate walls with brick.

1.10 cm X 2.1 cm (Door)

1.50 cm X 1.50 cm (Windows)

Country Wood

Rcc (10mm Steel bars)

C 5.3 Grade Cement)

(River Sand, Rock materials)

Cement - Plastered floor)

Cover a bed of hard broken

Cement - Concrete

Once every year.

I, SITALAKSHMI E. P. solemnly declares that the above details furnished are correct to the best of my knowledge.

Place : Ayyanthole

Date : 10/05/24



Signature of Manager

Principal
 Amrita Vidyalayam
 Ayyanthole, Thrissur