

**TO BE FILLED BY THE INSPECTING OFFICER**  
(ASSISTANT ENGINEER)

1 Name of officer AJAYAKUMAR P K  
2 Name of School AMRUTHA VIDHYALAYAM  
Location with name of education  
3 district/Sub district CHERUTHURUTHY/CHAVAKKAD/WADAKKANCHERY

4 Classification of building and size

RCC ROOF			
7.40X6.60X3.60	8NOS( GF )	7.40X6.60X3.60	8NOS( SF )
7.40X6.60X3.60	8NOS( FF )	7.40X6.60X3.60	8NOS( TF )
TOTAL		32NOS	

5 Period which certificate issued 2017-18

6 Nature of Defect if any NIL

- a) Foundation  
b) Super structure  
c) Doors and windows  
d) Wood work wrought and put up Nil  
e) Roof  
f) Flooring  
g) Miscellaneous

7 Any major defects notices which will render the building unsafe if any manner Nil

8 Whether maintenance work have been done properly Yes

9 Whether structure is sound enough or not for conducting classes Sound enough under normal weather and wind condition

Note: The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc  
Any additional observation deemed necessary for the certificate may be furnished seperately with the certificate

Certificate that the School was inspected by me on 17/01/2018 and found Fit to conduct classes for the period for the reason stated above

VALLATHOL NAGAR  
17/01/2018



Signature

*[Signature]*  
Asst. Engineer  
L.S.G.D. Section  
Vallathol Nagar Grama Panchayath