

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School

: AMRITA VIDYALAYAM

- | | | |
|--|---|-----------------|
| 1. Name of the Officer | : SUDEEP A.S | <u>G.F</u> |
| 2. Location | : ARAKKILAD | 57.41x9.65x3.70 |
| 3. Period for which the certificate is issued | : 2023-24 | 17.53x9.57x3.70 |
| 4. Types of building | : RCC | 10.19x6.15x3.70 |
| 5. Nature of defect if any | : | 6.75x7.27x3.70 |
| a) Foundation and basement | : | 3.90x2.70x3.70 |
| b) Superstructure | : | 3.23x0.87x3.70 |
| c) Doors and windows | : | <u>F.F</u> |
| d) Wood work wrought and put up | : | 17.53x9.57x3.70 |
| e) Roof | : | 57.41x9.65x3.70 |
| f) Flooring | : | 10.19x6.15x3.70 |
| g) Miscellaneous (Cracks if any) | : | 6.75x7.27x3.70 |
| 6. Any Major defects notices which will render the building unsafe in any manner | : NIL | <u>SF</u> |
| 7. Whether maintenance works have been done properly | : YES | 57.41x9.65x3.70 |
| 8. Whether the structure is sound or not for conducting classes | : The structure is sound enough to conduct classes under normal weather condition | 16.98x9.57x3.70 |

- Note:-
1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 24/8/2023
and found to be fit / unfit to conduct classes for the period 2023-24
for the reason stated above.

Place: Vatakara

Date: 25/8/2023



Assistant Executive Engineer
Local Infrastructure Development
& Engineering Wing
Vatakara Municipality
Assistant Engineer

APPLICATION FOR FITNESS CERTIFICATE OF SCHOOL BUILDINGS

1. Name of School : AMRITA VIDYALAYAM
2. Location with name of Educational District/Sub-District : PUTHUR POST, ARAKKILAD VADAKARA. 673104
3. Whether Fitness Certificate has been issued in previous year and if so, the number and date of the last certificate and the authority who issued it : YES
4. Classification of the building and site (for basis for classification see Annex I) :
 - i) Permanent (single or multi-storied) :
 - ii) Semi-Permanent :
 - iii) Temporary Shed :
5. Year of construction of different buildings : 2002
6. Short specification (score off the specification not applicable) :
 - i) Foundation and basement : RCC FRAME STRUCTURE
Rubble in lime / Cement mortar / Mud mortar / or laterite in lime mortar / Cement mortar / Mud mortar
 - ii) Superstructure : RCC FRAME STRUCTURE
Rubble in lime / Cement / Mud or brick Laterite in Lime / Cement for pillars with intermediate Walls with Sum died bricks
 - iii) Doors and windows Country wood (mention Species) : WOOD
 - iv) Wood work wrought and put up : Country wood (Mention species).
Wrought and put up country wood or wrought and put up and full or half bamboo for rafters / iron trusses
 - v) Kind of roof with Short and applications in materials used : RCC / Tiles Thatched / A.C. Sheets
 - vi) Flooring TILE, CEMENT : Cement plastered over / hard broken / stone concrete bedding / gravel concretes / gravel bedding / laterite chips or cow-dung washed.
RCC FRAME STRUCTURE
7. Whether regular maintenance attended to or not Period during which last maintenance was done : YES

I Bri. THAMUJA . K I. solemnly

declare that the above details furnished are correct to the best of my knowledge.

Place: VADAKARA

Date: 23-8-2023



[Signature]
Signature of Manager
Principal
AMRITA VIDYALAYAM
VADAKARA
Affiliation No: 930680