

AE/LSGD/MM/SF-21/24-25

FITNESS CERTIFICATE

To be filled by inspecting officer (Asst. Engineer)

- | | | |
|--|---|---|
| 1 Name of School | : | AMRITHA VIDYALAYAM |
| | : | MANANTHAVADY |
| 2 Name of Officer | : | Dhanush S.S |
| 3 Location | : | Mananthavady |
| 4 Period for which certificate is | : | 25.06.2024 to 31-05-2025 |
| 5 | : | RCC |
| Type of building | : | Building 1x6.60x6.3x3.6 Principal |
| | : | do 1x6.60x6.3x3.6 Office |
| | : | do 10x6.6x6.36 10 Class Room |
| | : | do 1x13.26x6.36x3.6 Lab |
| | : | first floor 14x6.6x6.36x3.6 14 Class Room |
| | : | do 2x13.26x6.36x3.60 2 Lab |
| | : | do 1x10x6.36x3.6+6.60x6.36 Laibrary |
| | : | do 1x6.60x6.36x3.6 Staff Room |
| | : | second floor 6.60x6.36x3.6 10 Class Room |
| 6 Nature of defect if any | : | Nil |
| a Foundation and basement | : | Nil |
| b Super structure | : | Nil |
| c Door and windows | : | Nil |
| d Wood work wrought and put up | : | Nil |
| e Roof | : | Nil |
| f Flooring | : | Nil |
| g. Miscellaneous | : | Nil |
| 7 Any major defect noticed which will render the building unsafe in any manner | : | Nil |
| 8 Weather maintenance works have been done properly | : | Yes |
| 9 Whether structure is sound for conducting classes | : | Safe under normal climatic conditions |

Note 1. The stability of the structure should be examined also with reference to the altitude intensity of wind exposure to flood etc..

2. Any additional observation if deemed necessary for the certificate may be furnished seperately with the certificate.

Certified that the School was inspected by me on 25/06/2024 and found to be fit to conduct classes for the period for the reasons stated above

Place Mananthavady
Date 25-06-2024

Signature
Designation



ASSISTANT ENGINEER
LSGD
MANANTHAVADY MUNICIPALITY