

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School

: AMRITA VIDYALAYAM

- | | | |
|--|---|--------------------------------|
| 1. Name of the Officer | : | SINDU. S. |
| 2. Location | : | NGO QUARTERS, VELLI MADUKUNNU |
| 3. Period for which the certificate is issued | : | 2025 - 2026. |
| 4. Types of building | : | RCC PERMANENT - MULTY STORIED. |
| 5. Nature of defect if any | : | GF - 6.10x6.50x3.70 - 10 Nos. |
| a) Foundation and basement | : | - 4.00x6.50x3.70 - 1 Nos. |
| b) Superstructure | : | 6.50x10.00x3.70 - 1 No. |
| c) Doors and windows | : | 18.90x5.40x3.70 - 1 No |
| d) Wood work wrought and put up | : | 6.50x6.50x3.70 - 1 No |
| e) Roof | : | |
| f) Flooring | : | |
| g) Miscellaneous (Cracks if any) | : | |
| 6. Any Major defects notices which will render the building unsafe in any manner | : | NO |
| 7. Whether maintenance works have been done properly | : | YES |
| 8. Whether the structure is sound or not for conducting classes | : | YES |
- FF - 12.30x6.50x3.70 - 3 Nos.
6.35x6.50x3.70 - 1 No
6.10x6.50x3.70 - 4 Nos.
6.50x6.10x3.70 - 2 Nos.
6.50x5.60x3.70 - 1 No
- SF - 24.80x6.50x3.70 - 1 No
6.40x6.50x3.70 - 1 No
6.15x6.50x3.70 - 6 Nos
6.55x6.10x3.70 - 3 Nos.

- Note:-
1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

The structure is sound for conducting classes under normal wind and weather conditions.

CERTIFICATE

Certified that the School was inspected by me on 26.05.2025
and found to be fit / ~~unfit~~ to conduct classes for the period 2025 - 2026
for the reason stated above.

Place: KOZHIKODE

Date: 30.05.2025



Assistant Engineer

Assistant Executive Engineer
Kozhikode Municipal Corporation